. Water Reserve

STATINTL

Tentative Itinerary Outline

for

051 07cR

0B0/ (Bes 5)

150/ Chis > /

smil

CRS

Visit of U.S.S.R. Group

on

Methods and Means of Automation and Remote Control in Water Resource Systems

June 14, 1974 - June 28, 1974

State Dept. declassification & release instructions on file

### Approved Release 2002/05/07: CIA-RDP79-00 A000600100032-6

Tentative Itinerary Outline for Visit of U.S.S.R. Group

on

Methods and Means of Automation and Remote Control in Water Resource Systems (June 14, 1974 - June 28, 1974)

June 14 - Friday

U.S.S.R. Group to arrive at Dulles Airport, Washington, D. C., direct Aeroflot Flight from Moscow

Met at Dulles by members and/or representatives of U.S. Work

Group and Mr. Harald Peterson from the Soviet Embassy

June 15 - Saturday
Free day to adjust to time change and to visit the Washington area

Leave Washington, D. C. - United 277 (Lunch 11:15 a.m. served in flight)

Arrive Lincoln, Nebraska - 2:30 p.m.

Met at Lincoln by Nessra, Dirmoyer and Fischback

Travel from Lincoln to Grand Island, Nebraska
Ground transportation provided by Central
Nebraska Public Pewer and Irrigation District
Visit University of Rebraska automated irrigation
research stations on route to Grand Island, Nebraska
Stay overnight in Grand Island, Nebraska

June 18 - Tuesday

Visit Central Nebraska Public Power and Trrigation
District automated canal and supervisory control center
at Gothenburg, Nebraska

Stay overnight in Jeffery Lodge, guests of Central
Nebraska Public Power and Trrigation District, at
Brady, Nebraska
(See Publication No. 1)

June 19 - Wednesday

Visit North Platte Experimental Station and Central
Nebraska Public Power and Irrigation District Platte
River Diversion Dam

Leave North Platte, Nebraska, Frontier # 561 10:43 a.m.
Arrive Sacramento, California 3:18 p.m.

Stay nights of June 19, 20, 21 in Sacramento
Ground transportation furnished by USBR

### Approved For Release 20 2/05/07): CIA RDP79-00768 A000600100032-6

Visit USER Region Mid-Pacific and State of California Department of Water Resources Offices and Control Centers (See Publication No. 2)

### June 21 - Friday

Visit Federal and State Water Resource features
in Sacramento River Delta area

### June 22 - Saturdov

Visit California Aqueduct and Westlands Water
District
Leave Frasno, California - United # 631
Arrive Los Angeles
Stay nights of June 22 and 23 in Los Angeles

# 5:25 p.m. 6:10 p.m.

### June 23 - Sunday

Free day at Disneyland - Los Angeles

### June 24 - Monday

Leave for Elythe, California.
Transportation functioned by USBN
Visit USBN/ARS Automation Research at
Palo Vende Trrigation District
(See Publication No. 3)
Continue by bus to Phoenix, Arizona
Stay overnight in Phoenix

## 8:00 a.m.

3:00 p.m.

4:20 p.m.

6:52 p.m.

## June 25 - Tuesday

Visit Salt River Project

(See Publication No. 4)

Supervisory Control Center and Automated Structures

Lunch guests of Salt River Valley Water Users Assn.

Leave Phoenix, Frontier # 106 (Dinner served in flight)

Arrive Denver

Stay nights of June 25 and 26 in Denver

### Approved For Release 2002/05/07: CIA-RDP79-05758A000600100032-6

# June 26 - Wednesday

•	0.20
Leave Hotel	8:30 a.m.
	9:00 a.m.
Arrive Denver Federal Center	7.00 asine
cyc we e P Work Groups on Joint	
Meeting of U.S./U.S.S.R. Work Groups on Joint	0-00 2-20
Research Program	9:00 a.m 3:30 p.m.
Transportation furnished by Bureau of	-
transportation fulfillshed by bareau of	
Reclamation	

# June 27 - Thursday

Leave Hotel Arrive Denver Federal Center Continue Work Group Meeting	8:30 a. 9:00 a.	
Visit Bureau of Reclamation Engineering		
DIOGESSING FACTORES	1:00 - 3:00 p.	• m •
(See Publication No. 5) Leave Denver - TWA # 252 - (Dinner served in	*	
flight)	4:00 p	
Arrive Washington - Dulles	9:09 p	• M •

# June 28 - Friday

Visit USSR Embassy and USBR Commissioner's Office Depart the United States

### List of Publications

- 1. Power Production and Irrigation Control Automated in Nebraska
- 2. Central Valley Project Annual Reports 1970, 1971, 1972 San Luis Unit - Central Valley Project
- 3. Preliminary Progress Report on Automation of Surface Irrigation
- 4. Major Facts About the Salt River Project
- 5. The Engineering Laboratories of the Bureau of Reclamation

# Approved Release 2002/05/07: CIA-RDP79-00765A000600100032-6

TRAVEL ITINERARY

US-USSR Joint Commission on Scientific and Technical Cooperation
"Methods and Means of Automation and Remote Control in Water Resource Systems"

			Leave			Source Systems
Date	Day	Time	Arrive	Place	Via	Remarks
ie 14,	1974Fri.	,	Ar.	Washington, D.CDulles	USSR	Aeroflot
<u>1e 16</u>	Sun.	11:15 am	Lv.	Washington, D.CNat'1		United 277
		12:09 pm	Ar.	Chicago - O'Hara		
:		1:05 pm	I.v.	Chicago - O'Hara		United 923
		2:35 pm	Ar.	Lincoln, Nebraska		
<u>1e 19</u>	Hed.	10:43 am	Lv.	North Platte, Nebraska		Frontier 561
		11:20 am	Ar.	Denver	-	
		2:05 pm	Lv.	Denver		United 379
		3:18 pm	Ar.	Sacramento, California		
ne 22	Sat.	5:25 pm	Lv.	Fresno, California	1	United 631
		6:10 pm	Ar.	Los Angeles		
ne 24	Mon.	8:00 an	Lv.	Los Angeles	Blythe	Cormercial Bus
			Ar.	Phoenix, Arizona		
ne 25	Tue	4:20 pr	Lv.	Phoenix, Arizona		Frontier 106
		6:52 pr	Ar.	Denver		
ne 27	Thur	4:00 pr	Lv.	Denver		TWA 252
		9:09pm	Ar.	Washington - Dulles		
	· .					
		Annrove	For Rela	ase 2002/05/07 : CIA-RDP79-00	7 <del>98<u>4</u>000800100</del>	032-6
i		Thhiose	A I OI INCIE	AGC LOULIVOIDI . CIM-INDI 19-001	23700000100	002 0

# Approved For Release 2002/06/07 : CIA-RDP79-00798A000600100032-6

### UNITED AIRLINES

	LaGuardía St. Louis	12:05 PM 1:29 PM		Y
Lv:		4:20 PM		\$
Ar:	Lincoln	5:25 PM	-	
Surface to	North Platte		•	
6/19 Lv:	North Platte	10:40 AM	FL 561	Y
Ar:	Denver	11:17 AM	_	
Lv:	H	2:05 PM	UA 379	Y
Ar:	Sacramento	3:17 PM	-	
Surface to	Fresno	•		
6/22 Lv:	Fresno	5:25 PM	UA 631	Y
Ar:	Los Angeles	6:10 PM	~. 0V 02T	1
Surface to	Phoenix			
6/25 Lv:	Phoėnix	4:35 PM	FL 106	S.
· Ar:		7:07 PM	dinner	IJ.
	Denver	3:50 PM	TW 252	Y
Ar:	Dulles	9:08 PM	dinner	

#### Approved For Release 2002/05/07: CIA-RDP79-00796A000600100032-6

### Itinerary for Delegation from the Academy of Sciences of the USSR

June 12 - 23, 1974

Academician Yuriy A. Ovchinnikov Academician Aleksandr M. Prokhorov Dr. Stepan G. Korneev Mr. A. A. Kulakov

NAS Staff Aide - Mr. Alan M. Campbell

June 12 Arrive New York City via Aeroflot #311 from Moscow at 7:30 p.m.

Met by representatives of National Academy of Sciences

Depart New York (JFK) via Allegheny Airlines #527 at 9:40 p.m. Arrive Baltimore, Maryland at 10:36 p.m.

Proceed to Sheraton Carlton Hotel in Washington at 16th and K Streets

#### June 13 - 16 Washington, D.C.

. 3

National Academy of Sciences (separate program for Washington is attached)

June 16 Leave hotel at 4:15 p.m. for Dulles International Airport

Depart Washington, D.C. (Dulles) at 6:10 p.m. via Northwest Airlines #91

Arrive Seattle, Washington at 8:34 p.m.

Met at Seattle airport and escorted to Washington Plaza Hotel

#### June 17 Seattle, Washington

University of Washington in Seattle

Hosts: Dr. Philip W. Cartwright, Executive Vice President, University of Washington

Dr. Edmond Fischer, Department of Biochemistry,

University of Washington

Dr. Ernest Henley, Department of Physics,

· University of Washington

Evening - Ranier Club

Itinerary Approved For Release 2002/05/07: CIA-RDP79-00798A000600100032-6

June 18 Depart Seattle at 8:25 a.m. via Northwest Airlines #72 Arrive Spokane, Washington at 9:12 a.m.

Entire day at EXPO 74

Depart Spokane at 10:15 p.m. via Northwest Airlines #59 Arrive Seattle at 11:02 p.m.

(Lodging at Washington Plaza Hotel)

June 19 Depart Seattle at 8:50 a.m. via Northwest Airlines #4
Arrive New York City (JFK) at 4:42 p.m.

Proceed to St. Moritz Hotel at 50 Central Park South

June 20 - 23 New York City

June 20 Free Day

June 21 10:00 a.m. Working session at American Council of Learned Societies, 345 East 46th Street
(Dr. Korneev and Mr. Kulakov - Dr. Allen Kassof and Mr. Daniel Matuszewski)

12:30 p.m. Luncheon hosted by American Council of Learned Societies at Century Club, 7 West 43rd Street (For Academicians Ovchinnikov, Prokhorov, Dr. Korneev, and Mr. Kulakov)

6:15 p.m. Cocktails at residence of Dr. Frederick Seitz, President of Rockefeller University, followed by dinner

June 22 Free Day

June 23 Depart New York City (JFK) at 9:30 p.m. via Aeroflot #312 Arrive Moscow at 3:35 p.m. on June 24

#### Approved For Release 2002/05/07: CIA-RDP79-00799A000600100032-6

Washington, D. C. Program for Delegation of the Academy of Sciences of the USSR

Academician Yu. A. Ovchinnikov, Vice President Academician A. M. Prokhorov, Academician Secretary for General and Applied Physics

Dr. S. G. Korneev, Head, Administration for Foreign Relations Mr. A. A. Kulakov, Deputy Head, Admin. for Foreign Relations

June 12 (Wed.)	evening	Arrive Washington, D. C proceed to Sheraton-Carlton Hotel
June 13 (Thur.)	morning	Meeting of Dr. Korneev and Mr. L. C. Mitchell regarding text of Inter-Academy Exchange Agreement for 1974 and 1975
	2:30 p.m. 5:00 p.m.	Meeting of Academies' delegations at NAS (Board Room) Adjournment
	5:15 p.m.	Appointment of Soviet Academy delegation with Dr. H. Guyford Stever, Science Advisor to the President and Director, National Science Foundation
	7:30 p.m.	Dinner at NAS given by Dr. Handler, Executive Dining Room
June 14 (Fri.)	10:00 a.m. 12:30 p.m.	Meeting of Academies' delegations at NAS (Room 280) Adjourn
	3:00 p.m.	Signing of Exchange Agreement at NAS, followed by reconvening of meeting of Academies' delegations (Room 280)
	5:30 p.m.	Adjournment
June 15 (Sat.)	9:30 a.m. 12:30 p.m.	Meeting of Academies' delegations at NAS (Board Room) Adjournment "
	12:45 p.m.	Lunch at NAS (Executive Dining Room)
June 16 (Sun.)	morning	Free
	afternoon	Free
•	4:30 p.m.	Depart hotel for Dulles International Airport
•	6:10 p.m.	Depart Washington, D.C. (Northwest Flight 91)
	8:34 p.m.	Arrive Seattle, Washington (3 hours time difference)